



PANZITTA SALES & SERVICE
72 George Avenue
Wilkes-Barre, PA 18705
570-822-6720 800-822-6720
www.panzittasales.com


ROTARY LIFT

**FC5710 ROLLING BRIDGE
PARTS BREAKDOWN**



| | |
|---|--------------------|
|  | ORDER _____ |
| | MODEL _____ |
| DATE INSTALLED: _____ | CAP. _____ |
| | LB. _____ |
| MANUFACTURED UNDER ONE OF THESE PATENTS 3258087 3279562 3317004 3331470 3621762 | |
| JACK S. N. ON PLUNGER BELOW SUPERSTRUCTURE | |
| ROTARY LIFT | |
| MADE IN _____ | REGISTERED COMPANY |
| | NPS C |


PANZITTA SALES & SERVICE
72 George Avenue
Wilkes-Barre, PA 18705
570-822-6720 800-822-6720
www.panzittasales.com



PANZITTA SALES & SERVICE
72 George Avenue
Wilkes-Barre, PA 18705
570-822-6720 800-822-6720
www.panzittasales.com

| FC5710 REPLACEMENT PARTS | | | |
|---------------------------------|--|-------------|-----------------|
| ITEM NO. | DESCRIPTION | QTY. | PART NO. |
| 1 | Upper Channel Assembly | 1 | FC5722 |
| 2 | Lower Channel Assembly | 1 | FC5720 |
| 3 | Telescoping End Section Assembly (see End Section breakdown) | 2 | FC5718 |
| 4 | Pump | 1 | FC5824 |
| 5 | Cylinder | 1 | FC5711-1 |
| 6 | Cylinder Shaft | 2 | FC5711-2 |
| 7 | Hose | 1 | FC5110 |
| 8 | Elbow | 1 | FC5185-45 |
| 9 | Adapter | 2 | FC5791 |
| 10 | Link Structure | 1 | FC5715 |
| 11 | Pillow Block Assy. | 2 | FC5723 |
| 12 | Pillow Block Assy. | 2 | FC5711-6 |
| 13 | Slider Block | 1 | FC5711-7 |
| 14 | Slider Block | 2 | FC5711-5 |
| 15 | Slider Block | 2 | FC5711-4 |
| 16 | 1/4"-20NC x 1/4" Lg. Cup Point Socket Set Screw | 2 | 40041 |
| 17 | Retainer | 16 | FC5185-60 |
| 18 | Stop Bolt | 4 | FD242-3 |
| 19 | Bushing | 1 | FC59-7 |
| 20 | Elbow | 1 | FC566-3 |
| 21 | Guard Assembly | 2 | FC5144-1 |
| 22 | Caution Decal | 1 | NP207 |
| 23 | Model Nameplate | 1 | NP93 |
| 24 | Caution Decal | 1 | NP260 |
| 25 | Op. Instruction Decal | 1 | NP310 |
| 26 | Capacity Decal | 1 | NP309 |
| 27 | 1/2"-13NC x 3/4" Lg. HHCS | 4 | 40256 |
| 28 | 1/2"-13NC x 4 1/2" Lg. HHCS (wide runway setting) | 2 | 40334 |
| | 1/2"-13NC x 1" Lg. HHCS (narrow runway setting) | | 40260 |
| 29 | 1/2"-13NC Nut | 2 | 40700 |

Telescoping End Section



| END SECTION PARTS | | | |
|-------------------|--|------|-----------|
| ITEM NO. | DESCRIPTION | QTY. | PART NO. |
| 1 | End Section | 1 | FC5719 |
| 2 | Roller | 2 | FC5717 |
| 3 | Axle | 2 | FC67-29 |
| 4 | Inner Guide | 2 | FC67-28 |
| 5 | Bearing | 4 | FC5277-20 |
| 6 | Cap. Pts. Glde.#88-132-1325-000 or equal | 2 | ----- |
| 7 | Spring | 2 | FC5341-29 |

PANZITTA SALES & SERVICE
 72 George Avenue
 Wilkes-Barre, PA 18705
 570-822-6720 800-822-6720
www.panzittasales.com